






Assembly instructions

DB01 Cabinet

design Cees Braakman
1954



Components









pastoe

pastoe
sleepboot 4
3991cn houten
the netherlands

info@pastoe.com
www.pastoe.com

Assembly instructions



pastoe

pastoe
sleepboot 4
3991cn houten
the netherlands

info@pastoe.com
www.pastoe.com